


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



FON	r DUT GmbH	HAND					tolerance			scale: 4:1	
	ED OR AY NOT WITHOUN	ΗĦ								material: SEE SHEET 1	
	MAY NO-Y WITHC	B√							dim. in mm		
	PIEC TY V	98						date	name	title:	
	E COPIED OR AND MAY NO PARTY WITHC	DRAWIN					drawn	16.09.15	Lehmenkühler	RECOMMENDED PANEL CUT-C	UT
							appd.	21.09.15	Fischer	D-SUB COMBINATION MALE 5W5P SOLDER CUwith open 4-40 UNC thread dwg no:	CUP
	ANY V ANY V O A TH COPY	CAD					norm				
		出					d-old				DIN-
	WING CED 1 D ON PER M	ALT						45 =		15K1A1666	А3
	DRAWINA CODUCED ASSED ON TTEN PERI	NOT	а	Original							ո։ 2
	THIS DRAWI REPRODUCE BE PASSED (WRITTEN PE OWNERSHIP	ĺ	rev.	description	date	name	4		71-6	part no: SEE SHEET 1	