


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Signal Contact
 - 3.1 Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
 - 3.2. Apply some solder to the solder tip of the soldering iron.
 - 3.3. Put tip to wire in solder cup.
 - 3.4. After 1 second bring in solder.
 - 3.5. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 4. Power Contact
 - 4.1 Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
 - 4.2. Apply some solder to the solder tip of the soldering iron.
 - 4.3. Put tip to wire in solder cup.
 - 4.4. After 1 second bring in solder.
 - 4.5. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 5. Remove soldering iron.
- 6. Wait until solder gets rigid again.
- 7. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



_										
	r JUT GmbH	HAND					tolerance			scale: 4:1
	C G									material: SEE SHEET 1
	TED OR TAY NOT Y WITHOL	ВУ							dim. in mm	
	∄Σ≿ ∷I	NG						date	name	title:
		DRAWING					drawn	22.09.15	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
	NY NOT BE NY WAY, AI A THIRD P, ION.						appd.	23.09.15	Fischer	D-SUB COMBINATION MALE 7W2P SOLDER CUP
	AY NG ANY V SION	ALTER CAD					norm			with closed 4-40 UNC thread
G MA	Σ ≥ C Si □ I						d-old			dwg no: DIN-
	E E E E						_	45 =		15K1A1703
	DRA ODU VSSE TEN ERSF	NOT	а	Original						sh: 2
	THIS DE REPROD BE PASS WRITTE OWNERS	00	rev.	description	date	name	7		11-6	part no: SEE SHEET 1