

## DIN W48×H24mm, W72×H36mm Loop Powered Digital Scaling Meter

### ■ Features

- Loop powered type: Power from measured input
- Measurement input: DC4-20mA
- Max. display range: -1999 to 9999
- High/low-limit display scale function
- Decimal point change function
- High/low-limit input correction function
- Display Max./Min. value monitoring function
- Changeable delay time of monitoring Max./Min. value
- Display cycle change function  
(Selectable 0.5 sec/1 sec/2 sec/3 sec/4 sec/5 sec)
- Error display function



**⚠ Please read "Safety Considerations" in the instruction manual before using.**

### ■ Ordering Information

M	4	N	S	-	N	A	
Measurement input							A DC4-20mA
Power supply							N Loop powered type
Measurement function							S Scaling
Size							N DIN W48×H24mm
							Y DIN W72×H36mm
Digit							4 9999 (4-digit)
Item							M Meter

### ■ Specifications

Model	M4NS-NA	M4YS-NA
Power supply	Loop powered type	
Display method	7-segment LED display (red)	
Character height	10mm	14mm
Display accuracy <sup>※1</sup>	F.S. 0.3% rdg ±1-digit	
Display cycle	0.5 sec/1 sec/2 sec/3 sec/4 sec/5 sec	
Resolution	12,000 resolution	
Max. display range	-1999 to 9999	
Setting type	Setting type with the front keys	
Measuring input range <sup>※2</sup>	DC4-20mA	
Self-diagnosis function	Error display function	
Insulation resistance	Over 100MΩ (at 500VDC megger)	
Dielectric strength	2,000VAC 50/60Hz for 1 min	
Vibration	Mechanical	0.75mm amplitude at frequency of 10 to 55Hz (for 1 min) in each X, Y, Z direction for 1 hour
	Malfunction	0.5mm amplitude at frequency of 10 to 55Hz (for 1 min) in each X, Y, Z direction for 10 min
Shock	Mechanical	300m/s <sup>2</sup> (approx. 30G) in each X, Y, Z direction for 3 times
	Malfunction	100m/s <sup>2</sup> (approx. 10G) in each X, Y, Z direction for 3 times
Environment	Ambient temperature	-10 to 50°C, storage: -25 to 60°C
	Ambient humidity	35 to 85%RH, storage: 35 to 85%RH
Unit weight	Approx. 44g	Approx. 110g

※1: Ambient temperature (25°C±5°C): F.S. 0.3% rdg of ±1-digit (-10 to 50°C: F.S. 0.4% rdg ±1-digit)

※2: Impedance between input lines: Max. 600Ω (based on 24VDC)

Please be aware that activating input power is based on 24VDC, and the recommended impedance also will be lowered if the activating power is lower.

※Environment resistance is rated at no freezing or condensation.

# Loop Powered Scaling Meter


## Unit Description

### ◎ M4NS-NA



1. Display value, parameter, error display
2. M, **MD** key: When enter into parameter group, return to RUN mode, after completing parameter setting

### ◎ M4YS-NA





3. **▲, □** key: When enter into the status of parameter setting
4. **▲, □** key: When enter into the status of parameter setting and move digit

SENSORS
CONTROLLERS
MOTION DEVICES
SOFTWARE



## Dimensions

(unit: mm)


### ◎ M4NS-NA





#### • Bracket





#### • Panel cut-out




### ◎ M4YS-NA



#### • Bracket




#### • Panel cut-out




(J) Temperature Controllers
(K) SSRs
(L) Power Controllers
(M) Counters
(N) Timers
(O) Digital Panel Meters
(P) Indicators
(Q) Converters
(R) Digital Display Units
(S) Sensor Controllers
(T) Switching Mode Power Supplies
(U) Recorders
(V) HMI
(W) Panel PC
(X) Field Network Devices

## ■ Parameter 0 Group (Monitoring Mode)



1. Pressing **MD** key to enter monitoring mode in RUN mode.
  2. Each Max./Min. value will be shown by pressing **[ ]** key in monitoring mode and Max./Min. value will be initialized by pressing **[ ]** key once more.
  3. If no key touched for 60 sec, it will return to RUN mode.
  4. When do not use monitoring function, set **00 5** for **P\_EBL** in parameter setting.

## Parameter 1 Group



※Press the **[MD]** key after changing the setting value of the parameter. the setting value is saved and it moves to next parameter.

After entering setting parameter, hold the **MD** key for 3 sec. it displays **rUn** and returns to RUN mode.

※After entering setting parameter, hold the **■** Key for 3 sec, it will return to RUN mode  
※If any key is untouched for 60 sec, it will return to RUN mode

※ If any key is untouched for 60 sec, it will return to Normal mode.

- : Enable to change or set Parameter.
- : Disable to change or set Parameter but enable to check the setting value in Parameter group.  
Disable to enter into the status of change setting value by pressing keys

# Loop Powered Scaling Meter

## Parameter

Display	Function	Setting range	Factory default
L-SC	Low scale	Low limit display value for 4mA input -1.999 to 9.999, -19.99 to 99.99, -199.9 to 999.9, -1999 to 9999	0400
H-SC	High scale	High limit display value for 20mA input 0000, 000.0, 00.00, 0.000	2000
dot	Decimal point	Set Decimal point position 0000, 000.0, 00.00, 0.000	00.00
I-nb.L	Input bias low	Correct the Low-limit value of display value (digit) -100 to 100	0000
I-nb.H	Input bias high	Correct the High-limit value of display value (%) 0.900 to 1.100	1000
PERt	Max./Min. time	See the Max./Min. value monitoring delay time (sec) 0 to 30	01.5
dI St	Display time	Selectable sampling period (sec) 0.5, 1.0, 2.0, 3.0, 4.0, 5.0	0.5 5
EPCt	Error %	Set % of HHHH/LLL display range 0, 1, 2, 3, 4	3
LoC	Lock	Set the lock function ON, OFF	OFF

(S) Sensors

(T) Controllers

(U) Motion Devices

(V) Software

(J) Temperature Controllers

(K) SSRs

(L) Power Controllers

(M) Counters

(N) Timers

(O) Digital Panel Meters

(P) Indicators

(Q) Converters

(R) Digital Display Units

(S) Sensor Controllers

(T) Switching Mode Power Supplies

(U) Recorders


(V) HMIs

(W) Panel PC

(X) Field Network Devices

## Connections


### ◎ M4NS-NA




### ◎ M4YS-NA



※ Use terminals of size specified below.




## Connections of Applications



## ■ Functions

### ◎ Display scale [L - 5C / H - 5C]

This function is to display the value setting certain Hi/Low limit value against DC4-20mA input. For example if set a=DC4mA, b=DC20mA and A, B as display value, it will be displayed a=A, b=B.



### ◎ Correction [*I\_nb.H* / *I\_nb.L*]

This function is to adjust the error of display value after calculating scale value for measuring input and also correct the input error of sensor etc.

*I\_nb.L*: -100 to 100 [Adjust deviation of low value]  
*I\_nb.H*: 0.900 to 1.100 [Correct gradient (%) of high value]  
E.g.) When display value is 0.0 to 500.0 against 4-20mA input, if the display value is "1.2" for 4mA input, set -12 (ignore the decimal point) as *I\_nb.L* value to display "0.0". It is enable to remove offset of Low display value.  
※ When completed above Low value setting then apply 20mA, if the display value is "500.5", the correction value will be  $5005/5000=0.999$ , set 0.999 as *I\_nb.H* value then enable to correct High value is  $5005 \times 0.999 = 5000$ . It is also ignore the decimal point.

### ◎ Display Max./Min. value monitoring [*PEUH* / *PEUL*]

This function is to monitor Max. value and Min. value by current display value then display its Data in *PEUH* mode and *PEUL* mode.

Enable to set delay time in *PEUL* mode to protect the wrong Data by initial over current and set table from 0 to 30 sec and start to monitor after delay time.

### ◎ Display cycle delay

It is difficult to display when the measuring input value is fluctuating. In this case it is able to make display value stable by delaying display cycle.

Display cycle can be changed in *d1 5E* mode of Parameter 2 (0.5s/1.0s/2.0s/3.0s/4.0s/5.0s).

If select 5.0 5, it will be the measuring input value on an average for 5 sec, then display it every 5 sec.

### ◎ Error display [*E.PCE*]

#### ● Error display

- ① When *LLLL* flashes,
  - 1) Input current is lower than 3% in 4-20mAADC  
 $(16mA \text{ scale}) LLLL \text{ will flash when it is under } 3.52mA$   
 $[16mA \times 3\% = 0.48mA] \rightarrow 4mA - 0.48mA = 3.52mA$
  - 2) When it is beyond Min. display value (-1999)  
[by display value]
- ② When *HHHH* flashes,
  - 1) Input current is higher than 3% in 4-20mAADC  
 $(16mA \text{ scale}) HHHH \text{ flash}$   
 $[16mA \times 3\% = 0.48mA] \rightarrow 20mA + 0.48mA = 20.48mA$ .
  - 2) When it is higher than 20.48mA.  
When it is beyond Max. display value (9999)  
[by display value]

#### ● Turn Error display off

*LLLL* and *HHHH* are displayed when input is out of measuring range, therefore it will be disappeared automatically when input returns to measuring range

#### ● Error setting and sort

It will display the error message according to the setting value which set % value against analog input range and set it in *E.PCE* mode by *[*, *]* key.

Display	Description
<i>E.PCE</i> 1	<i>LLLL / HHHH</i> are displayed when it is over 0% out DC4-20mA range
<i>E.PCE</i> 2	<i>LLLL / HHHH</i> are displayed when it is over 1% out DC4-20mA range
<i>E.PCE</i> 3	<i>LLLL / HHHH</i> are displayed when it is over 2% out DC4-20mA range
<i>E.PCE</i> 4	<i>LLLL / HHHH</i> are displayed when it is over 3% out DC4-20mA range
<i>E.PCE</i> 5	<i>L - 5C / H - 5C</i> are displayed always when it is out of DC4-20mA range