

Prohibition signs EN ISO 7010:2012

| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|--|--------|---------------|----------|---|--------|---------------|----------|
| General prohibition sign | P001 | GH H 2 | F P | No metallic articles or watches | P008 | GH H 2 | F P |
| No smoking | P002 | GH 12 | F P | Do not touch | P010 | GHH2 | F P |
| No open flame, fire, open ignition source and smoking prohibited | P003 | СНН2 | F P | Do not extinguish with water | P011 | СНН2 | F P |
| No thoroughfare | P004 | СНН2 | F P | No heavy load | P012 | СНН2 | F P |
| Not drinking water | P005 | GH H 2 | F P | No activated mobile phone | P013 | GH H2 | F P |
| No access for forklift trucks and other industrial vehicles | P006 | СНН2 | F P | No access for people with metallic implants | P014 | СНН2 | F P |
| No access for people with active implanted cardiac devices | P007 | GHH2 | F P | No reaching in | P015 | GHH2 | F P |


Prohibition signs EN ISO 7010:2012

| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|--------------------------------------|--------|-------|----------|---|--------|---------------|----------|
| Do not spray with water | P016 | GHH2 | F P | Do not obstruct | P023 | GH H 2 | F P |
| No pushing | P017 | СНН2 | F P | Do not walk or stand here | P024 | С Н Н2 | F P |
| No sitting | P018 | СН Н2 | F P | Do not use this incomplete scaffold | P025 | СНН2 | F P |
| No stepping on surface | P019 | GH H2 | F P | Do not use this device in a bathtub, shower or water-filled reservoir | P026 | GHH2 | F P |
| Do not use lift in the event of fire | P020 | СНН2 | F P | Do not use this lift for people | P027 | СНН2 | F P |
| No dogs | P021 | СНН2 | F P | Do not wear gloves | P028 | СНН2 | F P |
| No eating or drinking | P022 | СНН2 | F P | No photography | P029 | С Н Н2 | F P |


Prohibition signs EN ISO 7010:2012



If you need any customized sign, please contact our office: info@anro-safety.com




Prohibition signs EN ISO 7010:2012



| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|---|--------|-------|----------|--------------------------|--------|-------|----------|
| General mandatory action sign | M001 | GHH2 | F P | Wear safety footwear | M008 | GHH2 | F P |
| Refer to instruction manual/booklet | M002 | ОНН2 | F P | Wear protective gloves | M009 | СНН2 | F P |
| Wear ear protection | M003 | СН Н2 | F P | Wear protective clothing | M010 | СНН2 | F P |
| Wear eye protection | M004 | GH H2 | F P | Wash your hands | M011 | GH H2 | F P |
| Connect an earth terminal to the ground | M005 | GHH2 | F P | Use handrail | M012 | СНН2 | F P |
| Disconnect main plug from electrical outlet | M006 | СНН2 | F P | Wear a face shield | M013 | СНН2 | F P |
| Opaque eye protection must be worn | M007 | ОН Н2 | F P | Wear head protection | M014 | СНН2 | F P |

| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|--|--------|---------------|----------|---|--------|---------------|----------|
| Wear high-visibility clothing | M015 | СНН2 | F P | Use barrier cream | M022 | СНН2 | F P |
| Wear a mask | M016 | GH 12 | F P | Use footbridge | M023 | GH H 2 | F P |
| Wear respiratory protection | M017 | СНН2 | F P | Use this walkway | M024 | ОН Н2 | F P |
| Wear a safety harness | M018 | GH H2 | F P | Protect infants eyes with opaque eye protection | M025 | GH H2 | F P |
| Wear a welding mask | M019 | GHH2 | F P | Use protective apron | M026 | GHH2 | F P |
| Wear safety belts | M020 | СНН2 | F P | Check guard | M027 | ОНН2 | F P |
| Disconnect before carrying out maintenance or repair | M021 | GH H 2 | F P | Keep locked | M028 | GH H 2 | F P |





| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|---|--------|-------|----------|--|--------|---------------|----------|
| General warning sign | W001 | GHH2 | F P | Warning: Drop (fall) | W008 | GHH2 | F P |
| Warning: Explosive material | W002 | GH H2 | F P | Warning: Biological hazard | W009 | GH H2 | F P |
| Warning: Radioactive material or ionizing radiation | W003 | ОН Н2 | F P | Warning: Low temperature/ freezing conditions | W010 | СНН2 | F P |
| Warning: Laser beam | W004 | GH H2 | F P | Warning: Slippery surface | W011 | GHH2 | F P |
| Warning: Non-ionizing radiation | W005 | GHH2 | F P | Warning: Electricity | W012 | GH H 2 | F P |
| Warning: Magnetic field | W006 | СНН2 | F P | Warning: Guard dog | W013 | СНН2 | F P |
| Warning: Floor-level obstacle | W007 | СНН2 | F P | Warning: Forklift trucks and other industrial vehicles | W014 | СНН2 | F P |

| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|-----------------------------|--------|-------|----------|----------------------------------|--------|-------|----------|
| Warning: Overhead load | W015 | СНН2 | F P | Warning: Sharp element | W022 | CHH2 | F P |
| Warning: Toxic material | W016 | GHH2 | F P | Warning: Corrosive substance | W023 | GHH2 | F P |
| Warning: Hot surface | W017 | GHH2 | F P | Warning: Crushing of hands | W024 | GHH2 | F P |
| Warning: Automatic start-up | W018 | СНН2 | F P | Warning: Counterrotating rollers | W025 | СНН2 | F P |
| Warning: Crushing | W019 | СН Н2 | F P | Warning: Battery charging | W026 | ОН Н2 | F P |
| Warning: Overhead obstacle | W020 | СНН2 | F P | Warning: Optical radiation | W027 | ОНН2 | F P |
| Warning: Flammable material | W021 | СНН2 | F P | Warning: Oxidizing substance | W028 | ОНН2 | F P |







Combined signs

Combined signs

Size

Material

F P


















Custom-made signs



CREATE YOUR OWN SIGN


If you are looking for your own sign, please choose the right pictogram and add your own text.


We will print it for you on any material and in any size.


If you have any questions, please contact our office: info@anro-safety.com

Set of signs


It is also possible to order OHS labels in the form of the following sets. To order a specific set, please select needful pictogram from the Occupational Health and Safety section (p. 36 - 47) or the Chemical Labeling section (p. 60 - 61). All pictograms on the sheets are available in a format adapted to customer requirements.




















 (2)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)
 (3)</t





Additional health and safety signs

| Sign | Symbol | Size | Material | Sign | Symbol | Size | Material |
|---|--------|---------------|----------|---|--------|---------------|----------|
| No entry for unauthorized | V/03 | СНН2 | F P | Do not cover | V/30 | СНН2 | F P |
| Climb forbidden for unauthorized | V/21 | GH 12 | F P | Do not insert a needle | V/29 | GH H 2 | F P |
| Occur behind the swivel arm is prohibited | V/33 | ОН Н2 | F P | Do not fold | V/31 | СНН2 | F P |
| Use conductive shoes | G/33 | GHH2 | F P | Use face protection | G/09 | GHH2 | F P |
| Lift only with help | G/25 | СНН2 | F P | Use safety harness | G/27 | СНН2 | F P |
| Warning: milling wave | W/37 | ОН Н2 | F P | Warning: danger of tipping when rolling | W/35 | СНН2 | F P |
| Warning: crushing hands | W/19 | GH H 2 | F P | Warning: moving conveyor on track | W/33 | GH H 2 | F P |